


## FENCE STAPLES



Gage No.9 Bright or Galvanized.

Length in.	Spread at Shoulders	Approx. Number per lb
$\frac{7}{8}$	$\frac{1}{4}$	120
1	"	108
$1\frac{1}{8}$	"	96
$1\frac{1}{4}$	"	87
$1\frac{1}{2}$	"	72
$1\frac{3}{4}$	"	65

Length is measured from the point to the underside of loop.

## POULTRY NETTING STAPLES



Gage No. 14 Bright or Galvanized.

Length in.	Spread at Shoulders	Approx. Number per lb
$\frac{3}{4}$	$\frac{3}{16}$	480
$\frac{7}{8}$	"	416
1	"	352

Length is measured from the point to the underside of loop.

## HOOP STAPLES



Gage No.14 Bright or Galvanized.

Length in.	Spread at Shoulders	Approx. Number per lb
$\frac{1}{2}$	$\frac{3}{16}$	610
$\frac{5}{8}$	"	568

Length is measured from the point to the underside of loop.